



## 快拆实心锥



## 订购信息

QB1	-	1/4	-	PP
喷嘴型号		螺纹尺寸		材质代码

## 基本参数

在指定的压力下(以bar为单位)。

喷头型号	流量(升/分钟)										喷射角度(°)		
	0.5巴	0.7巴	1.5巴	2巴	3巴	4巴	5巴	6巴	7巴	10巴	0.5巴	1.5巴	6巴
QB1	0.25	0.38	0.54	0.62	0.74	0.85	0.94	1	1.1	1.3	-	58	53
QB2	0.65	0.76	1	1.2	1.5	1.7	1.9	2	2.2	2.6	43	50	46
QB3	0.98	1.1	1.6	1.9	2.2	2.5	2.8	3.1	3.3	3.9	52	65	59
QB3.5	1.1	1.3	1.9	2.2	2.6	3	3.3	3.6	3.9	4.5	43	50	46
QB5	1.6	1.9	2.7	3.1	3.7	4.2	4.7	5.1	5.5	6.5	52	65	59
QB6.5	2.1	2.5	3.5	4	4.8	5.5	6.1	6.7	7.1	8.4	45	50	46
QB10	3.3	3.8	5.4	6.2	7.4	8.5	9.4	10.2	11	13	58	67	61

## 快拆扇形



## 订购信息

QC5001	-	1/4	-	PP
喷嘴型号		螺纹尺寸		材质代码

## 基本参数

在指定的压力下(以bar为单位)。

喷头型号(在3巴时的喷射角度)					流量(升/分钟)									
55°	65°	80°	95°	110°	0.3巴	1巴	2巴	3巴	4巴	5巴	6巴	7巴	14巴	
QC5001	QC6501	QC8001	QC9501	QC11001	0.12	0.23	0.32	0.39	0.46	0.51	0.56	0.6	0.85	
QC5002	QC6502	QC8002	QC9502	QC11002	0.25	0.45	0.64	0.79	0.91	1	1.1	1.2	1.7	
QC5003	QC6503	QC8003	QC9503	QC11003	0.37	0.69	0.97	1.2	1.4	1.5	1.7	1.8	2.6	
QC5004	QC6504	QC8004	QC9504	QC11004	0.5	0.92	1.3	1.6	1.8	2	2.2	2.4	3.4	
QC5005	QC6505	QC8005	QC9505	QC11005	0.62	1.1	1.6	2	2.3	2.5	2.8	3	4.3	
QC5006	QC6506	QC8006	QC9506	QC11006	0.75	1.3	1.9	2.4	2.7	3.1	3.3	3.6	5.1	
QC5008	QC6508	QC8008	QC9508	QC11008	1	1.8	2.6	3.2	3.6	4.1	4.5	4.8	6.8	
QC5010	QC6510	QC8010	QC9510	QC11010	1.2	2.3	3.2	3.9	4.6	5.1	5.6	6	8.5	
QC5015	QC6515	QC8015	QC9515	QC11015	1.9	3.4	4.8	5.9	6.8	7.6	8.4	9	12.8	
QC5020	QC6520	QC8020	QC9520	QC11020	2.5	4.6	6.5	7.9	9.1	10.2	11.2	12.1	17.1	
QC5030	QC6530	QC8030	QC9530	QC11030	3.7	6.8	9.7	11.8	13.7	15.3	16.7	18.1	26	